

# Ultrasonic Oxygen Sensor (Model: US1000)

**User's Manual** 

(Version 1.0) Issue Date. 2022.09.30

Zhengzhou Winsen Electronics Technology Co., Ltd ISO9001 Certificated Company

# Statement

This manual's copyright belongs to Zhengzhou Winsen Electronics Technology Co., LTD. Without the written permission, any part of this manual shall not be copied, translated, stored in database or retrieval system, also can't spread through electronic, copying, record ways.

Thanks for purchasing our product. In order to let customers use it better and reduce the faults caused by misuse, please read the manual carefully and operate it correctly in accordance with the instructions. If users disobey the terms or remove, disassemble, change the components inside of the sensor, we shall not be responsible for the loss.

The specific such as color, appearance, sizes &etc., please in kind prevail.

We are devoting ourselves to products development and technical innovation, so we reserve the right to improve the products without notice. Please confirm it is the valid version before using this manual. At the same time, users' comments on optimized using way are welcome.

Please keep the manual properly, in order to get help if you have questions during the usage in the future.

Zhengzhou Winsen Electronics Technology CO., LTD.

# US1000 Ultrasonic Oxygen Sensor

# Profile

The US1000 ultrasonic oxygen sensor is mainly used in the detection of oxygen concentration and flow in oxygen concentrators and related products. It uses ultrasonic sensors to detect the propagation speed of ultrasonic waves in gas, and uses temperature compensation to accurately calculate oxygen concentration and flow.



### **Main Features**

\*Good consistency \*Real-time response \*High precision \*Good stability \*long lifespan \*Calibration-free

## **Applications**

\*Household oxygen generator \*Medical oxygen concentrator

## **Detection principle**

The propagation time of ultrasonic waves in a binary gas mixture changes with the concentration and flow of the two gases. According to this law, the gas concentration and flow velocity can be calculated at the same time without affecting the normal flow of the gas.

Winsでの 炜盛科技Zhengzhou Winsen Electronics Technology Co., Ltd

www.winsentech.com

	Model No.	US1000					
De	tection method	ultrasound					
	Detection gas	02					
	Measuring range	21% ~ 95.6%					
	Measurement accuracy	± 1.5%FS @(5 ~ 45)°C					
Concontration	Resolution	0.1%					
concentration		≤15s T90					
	Response time	(Can be customized according to customer					
		requirements, the fastest $\leq 1s$ )					
	Measuring range	0 ~ 10L/min					
	Measurement accuracy	±0.2L/min@(5 ~ 45)°C					
Flow	Resolution	0.1L/min					
FIOW		≤15s T90					
	Response time	(Can be customized according to customer					
		requirements, the fastest $\leq 1s$ )					
Working voltage		4.5 ~ 13.2V					
A	verage current	≤30mA					
Working environment		$0 \sim 55^{\circ}$ C; $0 \sim 95\%$ RH ( no condensation )					
Storage environment		-30 ~ 65°C; 0 ~ 95%RH ( no condensation )					
	Output signal	UART(3.3V)					
	Dimensions	120mm*30mm*30mm(L*W*H)					
	Weight	25g					
Lifespan		≥5 years					

**Table 1 - Technical Specifications** 

#### Pin sequence:



Figure 1 - Pin sequence

Terminal description: P1 model is PH2.0-3P (Spacing 2.0mm), P2 model is PH2.0-4P (Spacing 2.0mm).

#### Pin definition:

Pin name	Pin description
P1-1	VCC(4.5 ~ 13.2V)
P1-2	NC dangling
P1-3	GND
P2-1	VCC(4.5 ~ 13.2V)
P2-2	UART(RXD) Serial port receiving (3.3V ~ 5V)
P2-3	UART(TXD) Serial sending (3.3V)
P2-4	GND

#### Table 2 - Pin Definition

#### **Communication Description:**

#### 1. Hardware connection

Connect the VCC-RXD-TXD-GND of the sensor to the VCC-TXD-RXD-GND of the customer respectively, as shown in the figure below (the user side needs to use TTL level, if it is RS232 level, it must be converted). A typical interface circuit is as follows:



#### 2. Serial parameters

#### Table 3 - Serial port configuration

name	description				
Baud rate	9600				
Data bit	8 bits				
stop bit	1 bit				
Check digit	None				

#### 3. Protocol Description

start byte	length	order	data	checksum	
Head	Length	Command	Data	Checksum	
1Byte	1Byte	1Byte	nByte	1Byte	

Data shows:

Note: 1. The data are all hexadecimal data, 1Byte refers to single-byte unsigned number (0-255), nByte refers to n-byte unsigned number;

The high byte of double-byte data comes first, and the low byte follows.

Data name	Illustrate						
Start byte	The upper computer send is fixed at 0x11, and the sensor module response is						
	fixed at 0x16						
Length	= command length (1) + data length (n) (note: data length n can be 0)						
Order	The sensor executes the command, 0x01 is to read the oxygen data measured						
	by the sensor, and the rest are reserved.						

Email: sales@winsentech.com

# Leading gas sensing solutions supplier in China!



炜盛科技Zhengzhou Winsen Electronics Technology Co., Ltd

Data	The data sent by the host or the sensor, the length is n bytes, or there is no
	data (n=0)
Checksum	=(0xFF- (Head + Length + Command + Data))+1
	(Note: checksum = all values except the checksum are accumulated and
	inverted + 1)

#### 4. Example

	start byte	length	order	check								
				value								
host sends	11	01	01	ED								
	start byte	length	order	data (D1)	data (D2)	data (D3)	data (D4)	data (D5)	data (D6)	data (D7)	data (D8)	check
	Start byte	length	oraci	uutu (D1)	uutu (DZ)	uutu (D3)	uutu (D4)	uutu (D3)	uutu (DO)		uutu (DO)	value
sensor send	16	09	01	03	A7	00	0C	01	1B	00	00	0E

#### Note:

The sensor has two data output modes. In the response mode, it is recommended that the host send the interval not less than 0.5S, and the active upload mode of the sensor is to send a set of data in 1S.

#### Function:

Read O<sub>2</sub> measurement results

#### Data analysis:

D1 and D2 are concentration values, O2 concentration value = (D1\*256 + D2)/10 (Vol %)

D3 and D4 are flow values, O2 flow value = (D3\*256 + D4)/10 (L/min)

D5 and D6 are temperature values, O2 temperature value = (D5\*256 + D6)/10 (°C)

(Note: The temperature returned by the sensor is the temperature of the gas in the sensor chamber)

D7 and D8 are reserved data

#### **Example calculation results:**

Each value is hexadecimal data, it should be converted to decimal number when calculating

D1=0x03=3, D2=0xA7=167, O2 concentration value=(3\*256+167)/10=93.5%

D3=0x00=0, D4=0x0C=12, O2 flow value=(0\*256+12)/10=1.2L/min

D5=0x01=1, D6=0x1B=27, O2 temperature value= $(1*256+27)/10=28.3^{\circ}C$ 

#### Notes:

- When the sensor is installed and used, it is forbidden to touch the pins of the transducers at both ends of the sensor;
- Do not disassemble the sensor gas pipeline fixing screws at will;
- The air inlet and outlet holes of the sensor must not be blocked or polluted, and liquids and debris are prohibited from entering the sensor gas pipeline;
- The sensor should not be subject to excessive impact or vibration;
- Do not use if the shell is damaged or deformed;

#### **Product Size**







Zhengzhou Winsen Electronics Technology Co., Ltd
Add: No.299, Jinsuo Road, National Hi-Tech Zone, Zhengzhou 450001 China
E-mail: sales@winsentech.com
Website: www.winsentech.com

#### Unnoted tolerance is ±0.3mm